

**ASSESSMENT OF EROSION AND PLANT COVER
ON THE TRANS ALASKA PIPELINE
RIGHT OF WAY
MILEPOSTS 0 TO 800
VOLUME 2**

**PREPARED FOR
THE STATE PIPELINE COORDINATOR'S OFFICE
ALASKA DEPARTMENT OF NATURAL RESOURCES
SEPTEMBER, 1992**

**PREPARED BY
NANCY J. MOORE
ALASKA PLANT MATERIALS CENTER
DIVISION OF AGRICULTURE
ALASKA DEPARTMENT OF NATURAL RESOURCES**

TABLE OF CONTENTS

VOLUME 1

	<u>Page</u>
Summary	1
Introduction	1
Methods	1
How the Results are Reported	2
Results and Discussion	2
Conclusions and Recommendations	4
References	6
List of Tables	
Table 1. Species in Alyeska's 1977 Revegetation Seed Mixes	3
Table 2. List of Plant Symbols and Scientific Names	5
Section A	
Erosion and Plant Cover Data by Milepost	A-1 to A-31
Section B	
List of Plant Taxa by Milepost	B-1 to B-82

VOLUME 2

Section P	
Milepost Photographs 0 to 400	P-1 to P-181

VOLUME 3

Section P	
Milepost Photographs 401 to 800	P-182 to P-381

SECTION P
MILEPOST PHOTOGRAPHS




Milepost 1.





Milepost 3.





Milepost 5.





Milepost 7.





Milepost 9.





Milepost 11.





Milepost 12.







Milepost 16.



Milepost 17.













Milepost 28 in the floodplain.



























Photographs missing for
Mileposts 54 - 62.





Mileposts 63 and 64. Thermokarst activity (refers to all four photographs).







Photographs for Mileposts
68 and 69 are missing.

















Milepost 84 in the floodplain.



Milepost 85.





Milepost 87.





Milepost 89.





Milepost 91.





Milepost 93.





Milepost 95.





Milepost 97.





Milepost 99.





Milepost 101.





Milepost 103,











Milepost 111.






Milepost 113.





Milepost 115.





Milepost 117.





Milepost: 119.



Mileposts 120 - 123 on snowpad
(no photographs).



Milepost 125.





Milepost 127.





Milepost 129.





Milepost 130.




Milepost 131.





Milepost 133.






Milepost 135.





Milepost 137.





Milepost 139.





Milepost 141.





Milepost 143.





Milepost 144.



Milepost 145.





Milepost 147,





Milepost 149.





Milepost 151.





Milepost 153.





Milepost 153.





Milepost 155.





Mileposts 157 - 165 inaccessible,
Atigun Reroute Project.





Milepost 167.



Milepost 168.







Mileposts 172 - 172.2. After corrosion dig in 1992 - workpad is subsiding.







Thermokarst adjacent to workpad at approximately 174.8.



Milepost 175.







Milepost 179.











Milepost 191.





Milepost 194
taken from road.

Milepost 195 in the floodplain.





Milepost 197.





Milepost 199.





Milepost 203.





Milepost 205.





Milepost 207.





Milepost 209.





Milepost 211 in the floodplain.





Milepost: 213.





Milepost 215.






Milepost 217.





Milepost 219.





Milepost 221.



Milepost 222.





Milepost 223.







